



Risk Assessment for the Mobile Climbing Wall.

Hazard	Who/what may be harmed?	Recommendation	Risk Level	What needs to be done?	By When?
Fall from height	Participants/Instructor	Daily safety checks by instructor. Karabiners, helmets and harnesses checked prior to ascent	Low	Instructor trained in safe climbing practices	Ongoing
Descending onto waiting Participants	Participants/Instructor	Waiting participants kept at a safe distance from the climbing wall face	Low	Constant Supervision Barriers used as required	Ongoing
Falls due to loose handholds	Participants/Instructor	Handholds checked prior to climbing wall use	Low	Training and Supervision	Ongoing
Descent injury	Participant	Descent brief given to climbers prior to ascent	Low	Training and Supervision	Ongoing
Head injury from falling objects	Participant	Helmets worn	Low	Remove mobile phones etc.	Ongoing
Suspension injury from loose jewellery	Participant	Participants requested to remove or secure loose jewellery	Low	Training and Supervision	Ongoing
Injuries occurring during unsupervised use/access	Participant	Restricted access when not in use. Wall lowered after last daily session on multiple day bookings	Low	Training and Supervision	Ongoing
Auto Belay Failure	Participant	System checked and signed off prior to climbing. Daily, monthly and yearly maintenance carried out	Low	Training and maintenance	Ongoing
Injury as a result of improper behaviour	Participant	All climbers are fully briefed prior to climbing and supervised during their climbing	Low	Training and maintenance	Ongoing